

PO Box 368 Exeter, NH 03833 (603) 642-4921

cr1512s [co-ø1-cr1538s]

Packing Slip

DATE **INVOICE** #

2/11/2005

2249

BILL TO

Accounts Payable University of Miami PO Box 248066 Coral Gables, FL 33124-1421

SHIP TO

Aubri Steele Univ. of Miami / HBOI Marine Tech. Group 5600 US Hwy 1 North Fort Pierce, FL 34946

P.O. NUMBER	TERMS	SHIP	DUE DATE	VIA	F.O.B.
AA10078	Net 30	2/11/2005	3/13/2005	UPS	Seapoint

QUANTITY	ITEM CODE	DESCRIPTION		
1	REPAIR	SCF s/n 2403 7 (Separate Ship n		
1	REPAIR	SCF s/n 2282 PRECEIVED		
1	REPAIR	SCF s/n 2322		
1	REPAIR	SCF s/n 2323		
1	REPAIR	SCF s/n 2603		
1	REPAIR	SCF s/n 2613		
1	REPAIR	SCF s/n 2620		
1	CAL	SUVF s/n 6127 /) # A084 16 Feb 05		
		See attached worksheet for details		

of repairs and charges.

SHIP

Shipping

via UPS Ground Collect

acct. no. on file

TRK# 1ZV577300393690482

2403	needs new window; cal 45% low fz-30 gains, cal new window on one side; new LED on other side		\$220
2282	cal 45% low; one LED failed fz-50 gains, cal one new LED		100
2322	low sensitivity; one LED failed fz-60 gains, cal one new LED ("A")		100
2323	low sensitivity; LED connections corroded fz-50 gains, cal two new LEDs		100
2603	cal 20% low; chipped window fz-20 gains, cal 20% low one new LED ("A")	warranty	0
2613	both windows cracked fz-20 gains, cal replaced both windows/LEDs	warranty	0
2620	both windows cracked fz-15 gains, cal replaced both windows/LEDs	warranty	0
6127	cal/eval fz-600 everything OK		0